



Attorney Docket No. 392.1859
CGC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yukio TOYOZAWA, et al.

Application No.: 10/758,037

ATTENTION

Confirmation No.: 6132

CERTIFICATE OF CORRECTION

Filed: January 16, 2004

BRANCH

U.S. Patent No.: 6,859,007

Issued: February 22, 2005

For: SERVO MOTOR DRIVE CONTROL DEVICE

*Certificate
JUL 19 2005
of Correction*

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:


Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 7-8-05

By: 
John C. Garvey
Registration No. 28,607

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

© 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,859,007

DATED : February 22, 2005

INVENTOR(S) : Yukio TOYOZAWA, et al.

On the title page, at item (73), please change --Fanuc Ltd-- to --FANUC LTD--

Column 7, line 18, please change "θ(c)" to --ε(c)--.

Column 8, line 50, after the word "thereto", please delete ----.

Column 10, line 51, please change "(FIG. 1C)" to --(FIG. 11C)--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,859,007

No. of add'l copies
@ 50¢ per page

Ψ

Feb 19 2005

2005